

Land Subsidence Rate in the Buckeye Area, Maricopa County
 Based on Envisat Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
 Time Period of Analysis: 2.1 Years 02/25/2006 To 04/05/2008


© ESA 2006 - 2008

Explanation

02/25/2006 To 04/05/2008

- Land Subsidence Rate**
- Decorrelation/No Data
 - Greater 7 cm/yr (2.8 in/yr)
 - 5 - 7 cm/yr (2.0 - 2.8 in/yr)
 - 3 - 5 cm/yr (1.2 - 2.0 in/yr)
 - 2 - 3 cm/yr (0.8 - 1.2 in/yr)
 - 1 - 2 cm/yr (0.4 - 0.8 in/yr)
 - 0.5 - 1 cm/yr (0.2 - 0.4 in/yr)
 - 0 - 0.5 cm/yr (0 - 0.2 in/yr)

- Subsidence Feature
- Hardrock
- Earth Fissures
- Cities/Towns
- Interstate
- US
- State
- Roads
- Railway



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 1/7/2015

