

110°5'0"W

110°0'0"W

109°55'0"W

109°50'0"W


109°45'0"W

32°30'0"N

32°25'0"N

32°20'0"N

32°15'0"N



© ESA 2009 - 2010

**Total Land Subsidence in the Fort Grant Rd and Willcox Areas, Cochise County
Based on Envisat Satellite Interferometric Synthetic Aperture Radar (InSAR) Data**

Time Period of Analysis: 1.0 Years 01/20/2009 To 01/05/2010

Explanation

01/20/2009 To 01/05/2010

Total Land Subsidence

- Decorrelation/No Data
- Greater 40 cm (15.7 in)
- 25 - 40 cm (9.8 - 15.7 in)
- 15 - 25 cm (5.9 - 9.8 in)
- 10 - 15 cm (3.9 - 5.9 in)
- 6 - 10 cm (2.4 - 3.9 in)
- 4 - 6 cm (1.6 - 2.4 in)
- 2 - 4 cm (0.8 - 1.6 in)
- 1 - 2 cm (0.4 - 0.8 in)
- 0 - 1 cm (0 - 0.4 in)

- Subsidence Feature
- Hardrock
- Earth Fissures
- Cities/Towns
- Highways and Interstates**
- Interstate
- US
- State
- Roads
- Roads
- Railway



1:200,000

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
Projection: Transverse Mercator
Datum: North American 1983
Units: Meter
Created: 10/24/2014

