



**Total Land Subsidence in the Fort Grant Rd and Willcox Areas, Cochise County  
Based on ERS-1 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data**

© ESA 1992 - 1993

**Time Period of Analysis: 1.0 Years 11/12/1992 To 11/06/1993**

**Explanation**

11/12/1992 To 11/06/1993

**Total Land Subsidence**

- Decorrelation/No Data
- Greater 40 cm (15.7 in)
- 25 - 40 cm (9.8 - 15.7 in)
- 15 - 25 cm (5.9 - 9.8 in)
- 10 - 15 cm (3.9 - 5.9 in)
- 6 - 10 cm (2.4 - 3.9 in)
- 4 - 6 cm (1.6 - 2.4 in)
- 2 - 4 cm (0.8 - 1.6 in)
- 1 - 2 cm (0.4 - 0.8 in)
- 0 - 1 cm (0 - 0.4 in)

- Subsidence Feature
  - Hardrock
  - Earth Fissures
  - Cities/Towns
- Highways and Interstates**
- Interstate
  - US
  - State
  - Roads
  - Roads
  - Railway



0 1 2 4 6 8 Miles

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: [www.azgs.gov/EFC](http://www.azgs.gov/EFC)

Coordinate System: NAD 1983 UTM Zone 12N  
Projection: Transverse Mercator  
Datum: North American 1983  
Units: Meter  
Created: 10/24/2014

