

110°5'0"W

110°0'0"W

109°55'0"W

109°50'0"W


109°45'0"W

32°30'0"N

32°25'0"N

32°20'0"N

32°15'0"N



Total Land Subsidence in the Fort Grant Rd and Willcox Areas, Cochise County
 Based on ALOS-1 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data

© ASF 2006 - 2011
 © JAXA 2006 - 2011

Time Period of Analysis: 4.2 Years 12/06/2006 To 02/01/2011


Explanation

12/06/2006 To 02/01/2011

Total Land Subsidence

- Decorrelation/No Data
- Greater 40 cm (15.7 in)
- 25 - 40 cm (9.8 - 15.7 in)
- 15 - 25 cm (5.9 - 9.8 in)
- 10 - 15 cm (3.9 - 5.9 in)
- 6 - 10 cm (2.4 - 3.9 in)
- 4 - 6 cm (1.6 - 2.4 in)
- 2 - 4 cm (0.8 - 1.6 in)
- 1 - 2 cm (0.4 - 0.8 in)
- 0 - 1 cm (0 - 0.4 in)

- Subsidence Feature
- Hardrock
- Earth Fissures
- Cities/Towns
- Highways and Interstates**
- Interstate
- US
- State
- Roads
- Roads
- Railway



1:200,000

0 1 2 4 6 8 Miles

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 10/24/2014

