



**Land Subsidence Rate in the Hawk Rock Area, Maricopa and Pinal Counties**  
 Based on ERS-1 and 2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data  
 Time Period of Analysis: 8.0 Years 05/17/1992 To 04/19/2000

© ESA 1992 - 2000

**Explanation**

05/17/1992 To 04/19/2000

**Total Land Subsidence**

- Decorrelation/No Data
- Greater 7 cm/yr (2.8 in/yr)
- 5 - 7 cm/yr (2.0 - 2.8 in/yr)
- 3 - 5 cm/yr (1.2 - 2.0 in/yr)
- 2 - 3 cm/yr (0.8 - 1.2 in/yr)
- 1 - 2 cm/yr (0.4 - 0.8 in/yr)
- 0.5 - 1 cm/yr (0.2 - 0.4 in/yr)
- 0 - 0.5 cm/yr (0 - 0.2 in/yr)

- Subsidence Feature
- Hardrock
- Earth Fissures
- CAP Canal
- Highways and Interstates**
- Interstate
- US
- State
- Roads
- Railway



1:200,000



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: [www.azgs.gov/EFC](http://www.azgs.gov/EFC)

Coordinate System: NAD 1983 UTM Zone 12N  
 Projection: Transverse Mercator  
 Datum: North American 1983  
 Units: Meter  
 Created: 1/5/2015

