

Total Land Subsidence in the Willcox and Kansas Settlement Areas, Cochise County
 Based on ALOS-2 and Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data

© MDA 2011 - 2015
 © JAXA 2006 - 2011

Time Period of Analysis: 8.4 Years 12/06/2006 To 04/09/2015

Explanation


12/06/2006 To 04/09/2015

Total Land Subsidence

- Decorrelation/No Data
- Greater 40 cm (15.7 in)
- 25 - 40 cm (9.8 - 15.7 in)
- 15 - 25 cm (5.9 - 9.8 in)
- 10 - 15 cm (3.9 - 5.9 in)
- 6 - 10 cm (2.4 - 3.9 in)
- 4 - 6 cm (1.6 - 2.4 in)
- 2 - 4 cm (0.8 - 1.6 in)
- 1 - 2 cm (0.4 - 0.8 in)
- 0 - 1 cm (0 - 0.4 in)

- Subsidence Feature
- Hardrock
- Earth Fissures
- Highways and Interstates**
- Interstate
- US
- State
- Roads
- Railway

1:250,939



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 5/12/2015

