



Land Subsidence Rate in the Maricopa-Stanfield Sub-Basin, Pinal County
 Based on Envisat Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
 Time Period of Analysis: 1.9 Years 04/18/2007 To 02/27/2008

© ESA 2006 - 2008

Explanation

02/22/2006 To 02/27/2008

Land Subsidence Rate

- Decorrelation/No Data
- Greater 7 cm/yr (2.8 in/yr)
- 5 - 7 cm/yr (2.0 - 2.8 in/yr)
- 3 - 5 cm/yr (1.2 - 2.0 in/yr)
- 2 - 3 cm/yr (0.8 - 1.2 in/yr)
- 1 - 2 cm/yr (0.4 - 0.8 in/yr)
- 0.5 - 1 cm/yr (0.2 - 0.4 in/yr)
- 0 - 0.5 cm/yr (0 - 0.2 in/yr)

Subsidence Feature

Hardrock

Earth Fissures

Highways and Interstates

Interstate

US

State

Roads

Railway



0 1.5 3 6 9 12 Miles

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 11/17/2014

