


# Total Land Subsidence in the Ranegras Valley, La Paz County
## Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
**Time Period of Analysis: 2.1 Years 02/26/2013 To 04/05/2015**

© MDA 2013 - 2015

### Explanation

**02/26/2013 To 04/05/2015**

**Total Land Subsidence**

- Decorrelation/No Data
- Greater 40 cm (15.7 in)
- 25 - 40 cm (9.8 - 15.7 in)
- 15 - 25 cm (5.9 - 9.8 in)
- 10 - 15 cm (3.9 - 5.9 in)
- 6 - 10 cm (2.4 - 3.9 in)
- 4 - 6 cm (1.6 - 2.4 in)
- 2 - 4 cm (0.8 - 1.6 in)
- 1 - 2 cm (0.4 - 0.8 in)
- 0 - 1 cm (0 - 0.4 in)

- Subsidence Feature
- Hardrock
- CAP Canal

**Highways and Interstates**

- Interstate
- US
- State
- Roads
- Railway

1:125,000

0 0.5 1 2 3 4 Miles




Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Coordinate System: NAD 1983 UTM Zone 12N
Projection: Transverse Mercator
Datum: North American 1983
Units: Meter
Created: 4/8/2015