

Land Subsidence Rate in the Ranegras Valley, La Paz County
 Based on ERS-1 and 2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
Time Period of Analysis: 4.7 Years 06/08/1992 To 03/13/1997

© ESA 1992 - 1997

Explanation


06/08/1992 To 03/13/1997

Land Subsidence Rate

- Decorrelation/No Data
- Greater 7 cm/yr (2.8 in/yr)
- 5 - 7 cm/yr (2.0 - 2.8 in/yr)
- 3 - 5 cm/yr (1.2 - 2.0 in/yr)
- 2 - 3 cm/yr (0.8 - 1.2 in/yr)
- 1 - 2 cm/yr (0.4 - 0.8 in/yr)
- 0.5 - 1 cm/yr (0.2 - 0.4 in/yr)
- 0 - 0.5 cm/yr (0 - 0.2 in/yr)

- Subsidence Feature
- Hardrock
- CAP Canal
- Interstate
- US
- State
- Roads
- Railway

Highways and Interstates



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 1/6/2015

