

**Total Land Subsidence in the Butler Valley Area, La Paz County**  
 Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data  
**Time Period of Analysis: 2.0 Years 03/12/2024 To 03/26/2026**

© MDA 2024 - 2026

**Explanation**

03/12/2024 To 03/26/2026


Total Land Subsidence

- |                            |                            |
|----------------------------|----------------------------|
| Decorrelation/No Data      | Greater 40 cm (15.7 in)    |
| 25 - 40 cm (9.8 - 15.7 in) | 25 - 40 cm (9.8 - 15.7 in) |
| 15 - 25 cm (5.9 - 9.8 in)  | 15 - 25 cm (5.9 - 9.8 in)  |
| 10 - 15 cm (3.9 - 5.9 in)  | 10 - 15 cm (3.9 - 5.9 in)  |
| 6 - 10 cm (2.4 - 3.9 in)   | 6 - 10 cm (2.4 - 3.9 in)   |
| 4 - 6 cm (1.6 - 2.4 in)    | 4 - 6 cm (1.6 - 2.4 in)    |
| 2 - 4 cm (0.8 - 1.6 in)    | 2 - 4 cm (0.8 - 1.6 in)    |
| 1 - 2 cm (0.4 - 0.8 in)    | 1 - 2 cm (0.4 - 0.8 in)    |
| 0 - 1 cm (0 - 0.4 in)      | 0 - 1 cm (0 - 0.4 in)      |

- |                                 |
|---------------------------------|
| Subsidence Feature              |
| Hardrock                        |
| <b>Highways and Interstates</b> |
| Interstate                      |
| US                              |
| State                           |
| Roads                           |



1:122,439



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Coordinate System: NAD 1983 UTM Zone 12N  
 Projection: Transverse Mercator  
 Datum: North American 1983  
 Units: Meter  
 Created: 4/10/2026

