

Total Land Subsidence in the Elfrida Area, Cochise County
 Based on Sentinel-1 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
Time Period of Analysis: 1.0 Years 05/13/2025 To 05/08/2026


© ESA 2025 - 2026
 © ASF 2025 - 2026

Explanation

05/13/2025 To 05/08/2026

Total Land Subsidence

Decorrelation/No Data		Subsidence Feature
Greater 40 cm (15.7 in)		Hardrock
25 - 40 cm (9.8 - 15.7 in)		Earth Fissures
15 - 25 cm (5.9 - 9.8 in)		Interstate
10 - 15 cm (3.9 - 5.9 in)		US
6 - 10 cm (2.4 - 3.9 in)		State
4 - 6 cm (1.6 - 2.4 in)		Roads
2 - 4 cm (0.8 - 1.6 in)		Railway
1 - 2 cm (0.4 - 0.8 in)		
0 - 1 cm (0 - 0.4 in)		



1:210,000

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 5/19/2026

