


Land Subsidence Rate in the Elfrida Area, Cochise County
 Based on Sentinel-1 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
 Time Period of Analysis: 1.0 Years 05/13/2025 To 05/08/2026

© ESA 2025 - 2026
 © ASF 2025 - 2026

Explanation

- 05/13/2025 To 05/08/2026
- Land Subsidence Rate**
- Decorrelation/No Data
 - Greater 7 cm/yr (2.8 in/yr)
 - 5 - 7 cm/yr (2.0 - 2.8 in/yr)
 - 3 - 5 cm/yr (1.2 - 2.0 in/yr)
 - 2 - 3 cm/yr (0.8 - 1.2 in/yr)
 - 1 - 2 cm/yr (0.4 - 0.8 in/yr)
 - 0.5 - 1 cm/yr (0.2 - 0.4 in/yr)
 - 0 - 0.5 cm/yr (0 - 0.2 in/yr)
- Highways and Interstates**
- Interstate
 - US
 - State
 - Roads
 - Railway
- Other Features**
- Subsidence Feature
 - Hardrock
 - Earth Fissures



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 5/19/2026

