

Total Land Subsidence in the Sahuarita and Green Valley Areas, Pima County
 Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
Time Period of Analysis: 16.0 Years 05/15/2010 To 04/09/2026

© MDA 2010 - 2026



Explanation

05/15/2010 To 04/09/2026

Subsidence Feature
Hardrock
CAP Canal
Highways and Interstates
Interstate
US
State
Roads

Total Land Subsidence

Decorrelation/No Data
Greater 40 cm (15.7 in)
25 - 40 cm (9.8 - 15.7 in)
15 - 25 cm (5.9 - 9.8 in)
10 - 15 cm (3.9 - 5.9 in)
6 - 10 cm (2.4 - 3.9 in)
4 - 6 cm (1.6 - 2.4 in)
2 - 4 cm (0.8 - 1.6 in)
1 - 2 cm (0.4 - 0.8 in)
0 - 1 cm (0 - 0.4 in)



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 5/26/2026

