


Land Subsidence Rate in the McMullen Valley, La Paz and Maricopa Counties
 Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
Time Period of Analysis: 1.0 Years 03/31/2025 to 03/26/2026

© MDA 2025 - 2026

Explanation
 03/31/2025 To 03/26/2026

Land Subsidence Rate	Subsidence Feature
Decorrelation/No Data	Hardrock
Greater 7 cm/yr (2.8 in/yr)	Earth Fissures
5 - 7 cm/yr (2.0 - 2.8 in/yr)	Roads
3 - 5 cm/yr (1.2 - 2.0 in/yr)	Railway
2 - 3 cm/yr (0.8 - 1.2 in/yr)	Highways and Interstates
1 - 2 cm/yr (0.4 - 0.8 in/yr)	Interstate
0.5 - 1 cm/yr (0.2 - 0.4 in/yr)	US
0 - 0.5 cm/yr (0 - 0.2 in/yr)	State



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 4/10/2026

